MONTANA HISTORICAL AND

ARCHIECIURAL INVENI	ORY Site #	ant
Legal Description: Block 1, Lots 9 & 10, Helson Addition Address: 218 lst Ave. West		
Ownership: name: Donna Marie & Harko J. Vranish		L =
Epublic address: 218 1st Ave. West, Rounds	ip, Mt.	Roll # B2 Frame #19
Railroad Ave	Historic Name: Common Name: Date of Construction: Before 19: Architect: Builder:	20
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Original Owner John Roe Original Use: Residence Present Use: Residence	
3rd Street	☐ plat records/maps ☐ XE tax cards 1905 ☐	ded on 1912 map

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

A one-story, rectangular-shaped residence with intersecting crossing gables. composition shingle siding, and concrete over cinder block foundation. Roof is wood shingle & has interior brick chimney. Windows on main part of residence are wood frame, double hung with wood-surround trim. Front-facing gable roof covers projecting enclosed porch with fixed wood-frame, multi light windows, and coursed, fock-faced brick of varying lengths. Front porch extension has concrete front steps with iron railing. Rear of structure has shed roof addition. A one-story, mable-roof two car garage located to the side of the residence has two large sliding doors with vertical siding and outside mounted rail & rollers. Garage has horizontal wood siding and wood-shingle roof.

This is a neutral structure.

Location map or building plan with arrow north.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.

John Roe was a miner at the Roundup Coal Mine No. 3 in 1912, a trackman for the No. 3 mine in 1914, a teamster for Meagher Brothers (1916).

Source: Polk City Directories Chain of Ownership Cards

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

Structure is located in block with other small older residences along main highway into town. Addition of large front porch and rear shed roof extension has caused some loss of integrity of design. Use of composition shakes on structure and rock faced apron on enclosed front porch have caused loss of integrity of materials.

INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name_William Babcock	Acreage: Less than one acre
Address: 2920 Salish Ct., Missoula, Mt.	USGS Quad: Boundup, Mt.
Date: July 11, 1983	UTM's: