## MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY

Site #

	regal pescription: Dirock & Doc 4-3-0 Nelson Ad	dition	The second second
	Address: 308 First Avenue West		
	Ownership: name: James G. Rodeghiero		
1027 <b>*</b>	⊠ private address: 1313 First Street East Ro	undup, Mt.	Roll # Al3 Frame # 15
N		Historic Name:	
	Railvous Ave.		
1	1	Date of Construction: Before	tes documented
	: "	Architect:	4-12-12-12-12-12-12-12-12-12-12-12-12-12-
tas	to a	Builder:	
19	, ,	Original Owner: Ted Kelly	
12	49	Original Use: Garage - co	mmercial
9	15	Present Use: Vacant gara	3.ge
Street.	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Research Sources:	
3rd	امْنَا	abstract of title	city directories
3		plat records/maps	sewer/water permits
1.	*	1 pm	] obituaries
		building permit	biographies
1		□ Sanborn maps — dates: 1912, 192 Bibliography: area not m	20, before 1920 napped 1912
	1st Ave West	bibliography.	mphed TATS
	Location map or building plan with arrow north,		
Г	PHYSICAL DESCRIPTION. Describe		

CAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This is a square wood frame garage with a gable roof and a shed roof addition. Other features include wooden casement hung garage doors, fixed 3 light rectangular windows in wood surround, (boarded up) and sided in multi color checkerboard pattern asphalt shingles. There is no visible foundation.

This is a contributing structure.

J January 3	how the persons, important events, and/or historical patterns associated with the structure significance.
INTEGRITY: Assess the degree to which the property.	he structure/site, and surrounding area accurately convey the historical associations of the
asphalt checkerboard pate	he structure/site, and surrounding area accurately convey the historical associations of the is located on a busy commercial thoroughfare. The tern siding was put on many years ago, and has rials integrity. Now/eyer How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard pate	tern siding was put on many years ago, and has
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard pate caused some loss of mater still maintains integrity	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard path caused some loss of mater still maintains integrity.  INFORMATION VALUE: Explain how the extition.	tern siding was put on many years ago, and has rials integrity. Now / fret How ever this structure y of design, materials and craftsmanship.
asphalt checkerboard path caused some loss of mater still maintains integrity.  INFORMATION VALUE: Explain how the extition.	tern siding was put on many years ago, and has rials integrity. Now/eyer How ever this structure y of design, materials and craftsmanship.  Stant structure/site may demonstrate or yield information about its historic use or construction.
asphalt checkerboard path caused some loss of mater still maintains integrity  INFORMATION VALUE: Explain how the exition.  RM PREPARED BY:  The Elizabeth Wood	tern siding was put on many years ago, and has rials integrity. Now ever this structure y of design, materials and craftsmanship.  tant structure/site may demonstrate or yield information about its historic use or construction.  GEOGRAPHICAL INFORMATION:
asphalt checkerboard path caused some loss of mater still maintains integrity.  INFORMATION VALUE: Explain how the extition.	tern siding was put on many years ago, and has rials integrity. Now ever this structure y of design, materials and craftsmanship.  tant structure/site may demonstrate or yield information about its historic use or construction.  GEOGRAPHICAL INFORMATION: