MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY | Site

Legal Description: Block 12, Lot 10, Steen Address: 320 Sixth Street West Ownership: name: Phillip Gerald and Donna Book private address: 320 Sixth Street West	nder
S private address: 236 Sixth Street West, Roun	dup, Montana Roll # A5 Frame # 3
5th st. w. hill hill	Historic Name: Common Name: Date of Construction: 1920 1940's Green (at this site) Original Owner: "Chick" Green (at this site) Original Use: residence
ath Street West Location map or building plan with arrow north.	Research Sources: abstract of title

noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one story rectangular wood frame residence originally had an interesting gable roof with a shed roof enclosed front porch and a shed roof addition to the rear other features include a central brick stretcher bond brick chimney(that: was repaired at a later time). Two long rectangular fixed wood frame porch windows and a 6 light wood panel front door and boxed enclosed eaves. Modern features include side andkback shed additions, asphalt roofing, wide aluminum siding, alumin aluminum frame 1/1 and 4 light rectangular fixed and wind windows on the south and a cement foundation.

This is a neutral structure.

35. · · · · · · · · · · ·

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/s and surrounding area lend the property significance.	
	the state of the s
	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ø.	ert i kan aka ara a meta jir.
	the Army to the transport of the second section of the second
1.4 /5/ 1044 g	
· · · ·	
	•
and the second of the second	
INTEGRITY: Assess the degree to which the structu	ure/site, and surrounding area accurately convey the historical associations of the
This small house is located residences, some of which have be	ure/site, and surrounding area accurately convey the historical associations of the
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and	in a quiet neighborhood of all moved in een remodeled. This house was moved form another
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity	in a quiet neighborhood of all moved in een remodeled. This house was moved form another d steel siding added as well as several large shed
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity to the state of the st	in a quiet neighborhood of all moved in een remodeled. This house was moved form another d steel siding added as well as several large shed y of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity to the structure of	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shedy of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shedy of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in een remodeled. This house was moved form another is steel siding added as well as several large shed y of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another id steel siding added as well as several large shed y of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in een remodeled. This house was moved form another it steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structuproperty. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity and the structure of	in a quiet neighborhood of all moved in een remodeled. This house was moved form another it steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structuproperty. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the standard of the structure of the standard of the structure of the standard of	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shed of location, design and materials.
INTEGRITY: Assess the degree to which the structus property. This small house is located residences, some of which have be location, has had new windows and additions. It has lost integrity the structure of th	in a quiet neighborhood of all moved in seen remodeled. This house was moved form another is steel siding added as well as several large shed y of location, design and materials. The second of the