## MONTANA HISTORICAL AND

ANUNII	ECTURAL INVENT		Site #	
Legal Description:	Block 2, Lots 17, 18, & 19,	Ne	elson Addition	
Address:	334 1st Ave. West			
Ownership: name:	James Rodeghiero			
D public address:	1313 1st St. West, Roundup,	Mt	t.	Roll # A4 Frame # 5
	N.J.		Historic Name:	
Ru	ilroad Ave		Date of Construction: before 19 remodeled	20 Sestimated Section documented
		12.	Builder:	
•		3	Original Use: Peridence	
	*	1	Original Ose	
		7	. 1000/11 000.	
		V)	Research Sources:	
*		315		☐ city directories
		(7)	CCA.	sewer/water permits  obituaries
•				□ biographies
			☐ Sanborn maps — dates: 1912, 1920	0- before 1920
	- 1 - t t t t t t t t t t t t t t t t t			red by 1912 maps
ist	Ave West		Interview: Jim Rodeghic Chain of Cymership car Recorder's Of	ds, Clerk and

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one-story, square, wood-frame residence has a gable roof with a shed roof addition to the rear and a front gable enclosed entryway. Other features include an interior stretcher bond chimney, asphalt roofing, small extended eaves, modern slide aluminum frame windows and masonite shingles and vertical wood paneling exterior. The house has a cement foundation.

There is a rectangular wood frame garage on the property which has a gable roof with extended eaves, a 6-light fixed window and wood siding with corner boards. No door or foundation.

This is a neutral structure.

Location map or building plan with arrow north.

	•
¥	
	a a
	*
NTEGRITY: Assess the degree to which the structure/site, and property.	surrounding area accurately convey the historical associations of the
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old stru	esidential thoroughfare. Recent remodelin
This house is on a busy commercial/re with modern windows and siding has cause	esidential thoroughfare. Recent remodeling
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old stru	esidential thoroughfare. Recent remodelin
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.	esidential thoroughfare. Recent remodelin sed loss of integrity of materials. New acture. The addition of a gable front cau
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodeling sed loss of integrity of materials. New acture. The addition of a gable front cause
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old structure of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodelin sed loss of integrity of materials. New acture. The addition of a gable front cau
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old structure of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodelin sed loss of integrity of materials. New acture. The addition of a gable front cau
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodeling sed loss of integrity of materials. New acture. The addition of a gable front cause
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodelin sed loss of integrity of materials. New acture. The addition of a gable front cau
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodelin sed loss of integrity of materials. New acture. The addition of a gable front cau
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials	esidential thomographers. Describ
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old structure of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodeling sed loss of integrity of materials. New acture. The addition of a gable front cause
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old structure of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodeling sed loss of integrity of materials. New acture. The addition of a gable front causes and demonstrate or yield information about its historic use or construction.
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.  NFORMATION VALUE: Explain how the extant structure/site materials.	esidential thoroughfare. Recent remodeling sed loss of integrity of materials. New acture. The addition of a gable front causes ay demonstrate or yield information about its historic use or construction.
This house is on a busy commercial/re with modern windows and siding has caus materials completely cover the old struloss of integrity of design.	esidential thoroughfare. Recent remodel sed loss of integrity of materials. New acture. The addition of a gable front c