MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY

2 42 4 5 4 5 4 5	Site #	
Legal Description:	Block 11, Lot 3, Steen Addition	
Address:	411 Fifth Street West	
Ownership: name:	Rose Scharf Larson	
private address:	409 Fifth Street West, Roundup, MT	Bo

Roll # A12 Frame # 2

Common Name: Date of Construction: 1920 Architect: Bullder: Original Owner: Rose Scharf Larson Original Use: residence Present Use: residence Research Sources: abstract of title city directories sewer/water permits tax cards obituaries building permit obigraphies Sanborn maps - dates: don't include area Bibliography:
Location map or building plan with arrow north.

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance,

noting additions, alterations, and changes in materials. Discuss significant architectural features.

A small, one-story wood-frame residence with gable roof, with several shed roof rear extensions, horizontal beveled board siding and concrete foundation. Roof has interior brick chimney, wood shingles, eaves with fascia. Windows are wood-frame, double-hung 6/6 x 1/1, and sliding, with wood-surround. Numerous small evergreen trees in front yard obscure view of front doors and windows. Rear side porch has shed roof, fixed wood frame windows and wood frame door with panels and wood shingle siding. Adjoining shed extension with shed roof, wood shingle-siding and sheet metal roof is located at rear of residence.

5 . . Sign 5 . . .

This is a neutral structure.

	The Mark of the second of the
factor to	
	and the second s
χ	
* · · · · ·	
erra radioni es.	
This small residence is loc	site, and surrounding area accurately convey the historical associations of the
This small residence is located identes. It is several additions rear extension have caused a loss to the stant structure.	eated in a half-block of other small older res- and use of shake siding and metal roofing to s of materials and design.
This small residence is located idences. It is several additions rear extension have caused a loss stored and the second	cated in a half-block of other small older res- and use of shake siding and metal roofing to s of materials and design.
This small residence is located identes. It is several additions rear extension have caused a loss rear extension have rear extension have caused a loss rear extension have rear extension have rear extension have caused a loss rear extension have rear extension have rear extension have rear extension have rear	cated in a half-block of other small older res- and use of shake siding and metal roofing to s of materials and design.
This small residence is located idences. It is several additions rear extension have caused a loss stored and the second	cated in a half-block of other small older res- and use of shake siding and metal roofing to s of materials and design. Contain the state of the st