MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

A rectangular wood-frame carage with a gable roof, simulated brick composition siding with end boards, and wood frame, vertically hung, vertical board double garage door. Roof has composition sheet siding & eaves with fascia. Garage has shed roof extensions to east & west. East extension is open carport with vertical wood paneled siding. West extension has corrugated metal shed roof with vertical fibre board grooved siding with wood frame door with panels and 4 lights (with wood surround). This is a neutral structure.

and surrounding area lend the property significance.	tant events, and/or historical patterns associated with the structure/site
	•
INTEGRITY: Assess the degree to which the structure/site, and property.	surrounding area accurately convey the historical associations of the
This garage is located in a half blocated roof additions have accorded.	ck with no other structures. Posent
shed roof additions have caused a los	ss of integrity of design & materials.
NIFORM PROMINE FOR	
tion.	ay demonstrate or yield information about its historic use or construc-
	5
M PREPARED BY:	GEOGRAPHICAL INFORMATION:
M PREPARED BY: William Babcock	GEOGRAPHICAL INFORMATION: Acreage: Less than one acre
Milliam Dalassal	