

MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY

Site #




Legal Description: Block 1, Lots 11 & 12, Nelson's Second Addition

Address: 207 1st Ave. West

Ownership: name: Alfred Milliron

private address: 207 1st Ave. West, Roundup, Mt.
 public

Roll # A3 Frame # 8



Location map or building plan with arrow north.

Historic Name: _____

Common Name: _____

Date of Construction: 1920's estimated documented

Architect: _____

Builder: _____

Original Owner: _____

Original Use: residence

Present Use: residence

Research Sources:

- abstract of title
- city directories
- plat records/maps
- sewer/water permits
- tax cards 1910
- obituaries
- building permit
- biographies
- Sanborn maps — dates: 1920; after 1920

Bibliography:

Chain of Ownership cards, Clerk and Recorder's Office

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This small rectangular, one-story, wood-frame residence has a cement foundation, intersecting gable roofs and a shed roof enclosed rear porch. Other features include 1/1 double-hung windows, asphalt roofing, masonite siding and a narrow square interior stove pipe.

A partially dismantled older residence with a cement foundation, a gable roof covered in old wood planks and metal plates is located at the side of the property. This is a neutral structure.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This small house is on a busy thoroughfare near the commercial district. It has no features to associate it by materials or craftsmanship to an historic period. Modern materials and lack of upkeep have caused loss of integrity of materials and craftsmanship. The addition of a shed-porch has caused loss of design integrity.

INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction.

FORM PREPARED BY:

Name Elizabeth Wood

Address: Box 12, Roundup, Mt.

Date: July 9, 1983

GEOGRAPHICAL INFORMATION:

Acreage: Less than one acre.

USGS Quad: Roundup, Mt.

UTM's: _____