MONTANA HISTORICAL AND

ANUTIL	CIUNALINVENIO	Site #	N. A.
Legal Description:	Block 19, Lots 5 & 6, Northwes	st Townsite 2nd Addition	
Ownership: name:	Alvin E. & Helen R. Mock		一
public address:	410 4th Street West, Roundup,	Mt.	Roll # A12 Frame #17
<	- N	Historic Name: Common Name: Date of Construction: Addition Architect:	1973 🗀 estimated
5th Ave Wast	alley Hth Street West	Builder:Original Owner:Original Use:Present Use:	
Location	n map or building plan with arrow north.		

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This is a round roofed metal trailer with a wood-frame gable roof, a large room addition and a rear shed roof car port. The gable roof addition has vertical wood board siding, 6-light aluminum frame windows, 3-light wood-frame windows, cement foundation, and a fiberglass entry awning. The rear car port is a corrugated fiberglass cover.

This is a neutral structure.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property This mobile home residence is located on a block of mostly remodeled older home although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. IMPREPARED BY: [a. Elizabeth Wood		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. Less than one acre. USGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. Less than one acre. USGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: e. Elizabeth Wood ess: Box 12, Roundup, Mt. August 9, 1983 GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. USGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: e. Elizabeth Wood ess: Box 12, Roundup, Mt. August 2, 1983		*
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: Elizabeth Wood Ess: Box 12, Roundup, Mt. August 2, 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: Elizabeth Wood Ess: Box 12, Roundup, Mt. August 2, 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 9 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: BELIZABETH Wood CELIZABETH Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt. DSGS Quad: Roundup, Mt.		-
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: BELIZABETH Wood CELIZABETH Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt. DSGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: BELIZABETH Wood CELIZABETH Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt. DSGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: BELIZABETH Wood CELIZABETH Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt. DSGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. MPREPARED BY: BELIZABETH Wood CELIZABETH Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt. DSGS Quad: Roundup, Mt.		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
This mobile home residence is located on a block of mostly remodeled older home Although the mobile home part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 2 1983		
Although the mobile nome part is not compatible with an historic district, the additional structure built along it partially obscures the mobile home. The modern windows and siding on the structure make it a neutral residence. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: Elizabeth Wood Ess: Box 12, Roundup, Mt. August 9, 1983	INTEGRITY: Assess the degree to which the struct property.	ure/site, and surrounding area accurately convey the historical associations of the
INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: Elizabeth Wood Ess: Box 12, Roundup, Mt. August 9, 1983	ATTHOUGH THE MODILE HOME DAPT IS	not compatible with an historic district
INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. M PREPARED BY: a Elizabeth Wood ess: Box 12, Roundup, Mt. August 9, 1983	The modern windows and siding	on the structure make it a neutral residence
M PREPARED BY: e Elizabeth Wood ess: Box 12, Roundup, Mt. August 9, 1983 GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. USGS Quad: Roundup, Mt.		and to a neutral residence.
M PREPARED BY: e Elizabeth Wood ess: Box 12, Roundup, Mt. August 9, 1983 GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. USGS Quad: Roundup, Mt.		
M PREPARED BY: Bess: Box 12, Roundup, Mt. GEOGRAPHICAL INFORMATION: Acreage: Less than one acre. USGS Quad: Roundup, Mt.	INCORRATION VALUE. Fuelcie les des	
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983	tion.	cture/site may demonstrate or yield information about its historic use or construc-
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983		
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983		
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983		
Elizabeth Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt.		
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983		
Elizabeth Wood Box 12, Roundup, Mt. August 9, 1983 August 9, 1983		
Elizabeth Wood Acreage: Less than one acre. USGS Quad: Roundup, Mt.	M PREPARED BY:	GEOGRAPHICAL INFORMATION:
Box 12, Roundup, Mt. USGS Quad: Roundup, Mt.	e Elizabeth Wood	
August 9 1983	ess: Box 12, Roundup, Mt.	
	Annual 0 4097	UTM's: