



# MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY

Legal Description: <u>Block 48, Lot 2 &amp; 3, Roundup Second Addition</u> Address: <u>415 Third Street West</u> Ownership: name: <u>James E. Langan</u> <input checked="" type="checkbox"/> private <input type="checkbox"/> public address: <u>1202 First Street East, Roundup, Mt.</u>	Site # _____  Roll # <u>A12</u> Frame # <u>9</u>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------

<div style="text-align: center;">                 N →             </div> <div style="text-align: center; margin-top: 20px;">                 alley             </div> <div style="text-align: center; margin-top: 20px;">  </div> <div style="text-align: center; margin-top: 20px;">                 3rd Street West             </div> <p style="font-size: small; margin-top: 20px;">Location map or building plan with arrow north.</p>	Historic Name: _____ Common Name: _____ Date of Construction: <u>1914</u> <input checked="" type="checkbox"/> estimated <input type="checkbox"/> documented Architect: _____ Builder: <u>(probably) Thomas W. Peppard</u> Original Owner: <u>Mary A. Peppard</u> Original Use: <u>Residence</u> Present Use: <u>Residence</u> Research Sources: <input type="checkbox"/> abstract of title <input type="checkbox"/> city directories <input type="checkbox"/> plat records/maps <input type="checkbox"/> sewer/water permits <input checked="" type="checkbox"/> tax cards <input type="checkbox"/> obituaries <input type="checkbox"/> building permit <input type="checkbox"/> biographies <input checked="" type="checkbox"/> Sanborn maps — dates: <u>1912, 1920, Before 1920</u> Bibliography: <u>Area not mapped 1912</u>  Chain of Ownership cards, Clerk and Recorder's Office
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**PHYSICAL DESCRIPTION:** Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This square shaped one story wood frame residence has an original L-Shaped intersecting gable roof, and additional gable and shed roof rear additions, as well as a gable roof car port and recessed under the front eaves, an open full front porch. Other features include wood roof shingles, extended eaves, exposed rafters, with brackets and purlins, decorative gable face board, small eight-light fixed rectangular gable window, 12/1 double-hung front windows with narrow 6/6 double-hung side lights, 6/1 small double-hung windows and wood shingle siding with fish-scale shingles in the gable area. There is a small wood (1x1) balcony with open railing below the small eight-light gable window. The open front porch has shingle solid rails with square wood pillars with cap and base. The car port support and posts are battered pillars, wood shingled, and square cut wood pillars with capitals and base. There is a cement foundation under the house and wood board foundation under the porch. Modern materials include aluminum storm windows, and a cement covered brick chimney.

This building is a good example of a shingled bungalow residence.  
 This is a contributing structure.

**HISTORICAL SIGNIFICANCE:** Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.

Thomas W. Peppard was a carpenter for C.H. Chamberlain general contractors, in 1912-1913. Mary Peppard owned the property from 1913-1914.

Source: Polk City Directory

**INTEGRITY:** Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This residential neighborhood is mostly larger older unremodeled homes. This home has excellent integrity of craftsmanship (multilight windows, pillars) and materials (shingle siding and windows) and has some loss of integrity of design due to rear additions, but still retains good design integrity.

**INFORMATION VALUE:** Explain how the extant structure/site may demonstrate or yield information about its historic use or construction.

**FORM PREPARED BY:**

Name Elizabeth Wood

Address: Box 12, Roundup, Mt.

Date: August 10, 1983

**GEOGRAPHICAL INFORMATION:**

Acreage: Less than one acre.

USGS Quad: Roundup, Mt.

UTM's: